

Table manufacturing process





Fabrication

The steel is cut to length, de-burred and then welded together. A fully welded frame is superior in strength, to a traditional bolt together method.



2

Powdercoating

The welds are freed of any spatter or burrs prior to the frames being cleaned and primed. The powder colour of your choice is applied before being baked in the oven.



3

Assembly

Once the top has been cut to shape and edged, it is screwed onto the base of the table and nylon feet glides or castors are fitted for floor protection.





QA & Wrapping

The final Quality Assurance check is completed prior to each table being bagged and labelled. During this process the tables are checked to ensure they meet stringent quality standards.

Quality checkpoints include:

- Scratches on the table frames
- Scratches on the table top
- Ensuring the table sits level
- Colours/finishes according to all clients' specifications.





